



Office of the Superintending Engineer, RWS&S Division, Balangir ☎-(06652)232173(O),
e-mail: eerwss_blg@nic.in, fax - (06652) 230211

To,
The Headmaster
Balangir Public School, Balangir

Sub- Test report of water sample.

Sir,

With reference to the above subject, I am directed to furnish here with the test report for your information.

Encl. As above – Test report one sheet

Yours faithfully

Sahar 24.09.22
PRINCIPAL
Balangir Public School
Balangir-767001 (Odisha)

JK 08/03/22
Laboratory Chemist
RWS&S Division, Balangir

TEST REPORT OF WATER SAMPLE

Date of Collection : 05/03/2022
Collected By : Sri Uchhab Ghibela
Date of Receive : 07/03/2022
Date of Test : 07.03.2022 & 08.03.2022
Date of Submission Report : 08.03.2022
Lab Ref No : DLL/BGR-61/2022
District : Balangir
Block : Balangir
G.P : Balangir
Source : Well
Location : Balangir Public School, Hatisalpada, Balangir

S.N	Location	Source	pH	Turbidity NTU	Hardness Mg/l as CaCo3	Alkalinity Mg/l	Chloride Mg/l	Iron Mg/l	Fluoride Mg/l	TDS Mg/l
1	Balangir Public School, Hatisalpada, Balangir	Well	7.1	0.11	114	34	20	0.09	0.31	132

S.N	Quality Parameter	Unit	As per BIS	
			Desirable Limit	Permissible Limit
1	pH		6.5	8.5
2	Turbidity	NTU	1	5
3	Hardness	Mg/l as CaCo3	200	600
4	Alkalinity	Mg/l	200	600
5	Chloride	Mg/l	250	1000
6	Iron	Mg/l	0.3	1.0
7	Fluoride	Mg/l	1.0	1.5
8	TDS	Mg/l	500	2000

Sahak 24.09.22
PRINCIPAL
Balangir Public School
Balangir-767001 (Odisha)

[Signature]
08/03/22
Laboratory Chemist
RWS&S Division, Balangir